

Westridge Elementary School - Sampled 6/28/16			
CustomerSampleNumber	Description	Lead Result	Units
47500-115-S1	Art Room Sink	4.5	ppb
47500-115-S2	Art Room Sink	4.4	ppb
47500-115-S3	Art Room Sink	4.6	ppb
47500-115-S4	Art Room Sink	4.7	ppb
47500-112H-DF	Hallway Drinking Fountain near Cafeteria	<0.1 *	ppb
47500-C-9H-DF	Hallway Drinking Fountain near Classroom C-2	0.5	ppb
47500-C-10-S	Hallway Sink in C-Pod	0.5	ppb
47500-C-8H-DF	Hallway Drinking Fountain near Classroom C-6	1.0	ppb
47500-A-9H-DF	Hallway Drinking Fountain near Classroom A-6	0.5	ppb
47500-A-10-S	Hallway Sink in A-Pod	0.9	ppb
47500-A-8H-DF	Hallway Drinking Fountain near Classroom A-2	0.5	ppb
47500-110H-DF	Hallway Drinking Fountain near Teacher's Lounge	<0.1 *	ppb
47500-130-S	Sink in Teacher's Lounge	0.5	ppb
47500-RE-017-DF	Drinking Fountain in Temp RE-017	6.8	ppb
47500-R1-224-DF	Drinking Fountain in Temp R1-224	1.0	ppb
47500-106-S1	Food Service Sink	2.5	ppb
47500-106-S2	Food Service Sink-Wash/Rinse/Sanitize	2.6	ppb
47500-106-S3	Food Service Sink-Wash/Rinse/Sanitize	1.0	ppb
47500-123-S	Sink in Office Planning Area	6.0	ppb
47500-120-S	Sink in Clinic	0.6	ppb
47500-1-SWB	Sink with Bubblers in Kindergarten Classroom 1	0.7	ppb
47500-2-SWB	Sink with Bubblers in Kindergarten Classroom 2	0.4	ppb
47500-136-S	Sink in the Library Workroom	0.7	ppb
47500-B-9H-DF	Hallway Drinking Fountain near Classroom B-6	3.6	ppb
47500-B-10H-S	Hallway Sink in B-Pod	0.4	ppb
47500-B-8H-DF	Hallway Drinking Fountain near Classroom B-2	2.4	ppb

\* This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.