

| Ralston Elementary School - Sampled 6/16/16                            |                                                          |             |       | Resampled 8/19/16 or 3/24/17 |       |
|------------------------------------------------------------------------|----------------------------------------------------------|-------------|-------|------------------------------|-------|
| CustomerSampleNumber                                                   | Description                                              | Lead Result | Units | Lead Result                  | Units |
| 35000-208-S                                                            | Sink in Clinic                                           | 0.8         | ppb   |                              |       |
| 35000-208A-S                                                           | Sink in Clinic Restroom                                  | 2.7         | ppb   |                              |       |
| 35000-203H-DFL                                                         | Hallway Drinking Fountain near Office/Left               | 0.7         | ppb   |                              |       |
| 35000-203H-DFR                                                         | Hallway Drinking Fountain near Office/Right              | 0.7         | ppb   |                              |       |
| 35000-214-SWB                                                          | Sink with Bubbler in Classroom 214                       | 39.4        | ppb   | 6.1*                         | ppb   |
| 35000-216-SWB                                                          | Sink with Bubbler in Classroom 216                       | 22.3        | ppb   | 5.8*                         | ppb   |
| 35000-220-S                                                            | Sink in Bookroom                                         | 55.2        | ppb   | Repairs Pending              |       |
| 35000-220B-S                                                           | Sink in Restroom near Bookroom                           | 10.2        | ppb   |                              |       |
| 35000-222-S                                                            | Sink in Teacher's Lounge                                 | 5.0         | ppb   |                              |       |
| 35000-222A-S                                                           | Sink in Teacher's Lounge Restroom                        | 5.6         | ppb   |                              |       |
| 35000-224A-S                                                           | Sink in Office Restroom                                  | 13.3        | ppb   |                              |       |
| 35000-228-SWB                                                          | Sink with Bubbler in Office                              | 187.3       | ppb   | Repairs Pending              |       |
| 35000-306-S                                                            | Sink in Teacher's Lounge                                 | 0.5         | ppb   |                              |       |
| 35000-306A-S                                                           | Sink in Teacher's Lounge Restroom                        | 0.2         | ppb   |                              |       |
| 35000-310-S1                                                           | Sink in Community Room                                   | 9.3         | ppb   |                              |       |
| 35000-310-S2                                                           | Sink in Community Room                                   | 22.2        | ppb   | 4.8*                         | ppb   |
| 35000-314H-DFL                                                         | Hallway Drinking Fountain near Custodial Closet/Left     | 14.1        | ppb   |                              |       |
| 35000-314H-DFR                                                         | Hallway Drinking Fountain near Custodial Closet/Right    | 29.9        | ppb   | Repairs Pending              |       |
| 35000-318-SWB                                                          | Sink with Bubbler in Classroom 318                       | 6.9         | ppb   |                              |       |
| 35000-229-S1                                                           | Art Room Sink                                            | 20.2        | ppb   | Repairs Pending              |       |
| 35000-229-S2                                                           | Art Room Sink                                            | 12.2        | ppb   |                              |       |
| 35000-229-S3                                                           | Art Room Sink                                            | 11.6        | ppb   |                              |       |
| 35000-229-S4                                                           | Art Room Sink                                            | 189.0       | ppb   | Repairs Pending              |       |
| 35000-225H-DF                                                          | Drinking Fountain in Hallway near Custodial Closet       | 1.5         | ppb   |                              |       |
| 35000-225H-WBFS                                                        | Hallway Water Bottle Filling Station                     | 2.2         | ppb   |                              |       |
| 35000-102B-DFL                                                         | Drinking Fountain in Hallway near Custodial Closet/Left  | 0.8         | ppb   |                              |       |
| 35000-102B-DFR                                                         | Drinking Fountain in Hallway near Custodial Closet/Right | 1.4         | ppb   |                              |       |
| 35000-104-SWB                                                          | Sink with Bubbler in Kindergarten Classroom 104          | 0.4         | ppb   |                              |       |
| 35000-106-SWB                                                          | Sink with Bubbler in Kindergarten Classroom 106          | 0.4         | ppb   |                              |       |
| 35000-108-SWB                                                          | Sink with Bubbler in Kindergarten Classroom 108          | 0.2         | ppb   |                              |       |
| 35000-107-SWB                                                          | Sink with Bubbler in Classroom 107                       | 0.7         | ppb   |                              |       |
| 35000-109-SWB                                                          | Sink with Bubbler in Classroom 109                       | 0.5         | ppb   |                              |       |
| 35000-111-SWB                                                          | Sink with Bubbler in Music Room                          | 0.2         | ppb   |                              |       |
| 35000-302-S1                                                           | Food Service Sink                                        | 2.7         | ppb   |                              |       |
| 35000-302-S2                                                           | Food Service Sink                                        | 3.4         | ppb   |                              |       |
| 35000-302-S3                                                           | Food Service Sink                                        | 2.5         | ppb   |                              |       |
| 35000-302B-S                                                           | Sink in Kitchen Locker Room                              | 0.6         | ppb   |                              |       |
| 3500-218-SWB                                                           | Sink with Bubbler in Classroom 218                       | 33.4        | ppb   | 4.1**                        | ppb   |
| *Sampled on 8/19/16 after elevated fixtures were removed and replaced. |                                                          |             |       |                              |       |
| **Sampled on 3/24/17 after elevated fixture was removed and replaced.  |                                                          |             |       |                              |       |