

| Bergen Meadow Elementary - Sampled 6/16/16 | | | | Resampled** 8/16/16 | |
|--|--|-------------|-------|---------------------|-----------------|
| CustomerSampleNumber | Description | Lead Result | Units | Lead Result | Units |
| 04700-172H-DF | Hallway Drinking Fountain | 3.6 | ppb | | |
| 04700-219-SWBL | Clinic Sink with Bubbler/Left | 8.7 | ppb | | |
| 04700-219-SWBR | Clinic Sink with Bubbler/Right | 15.3 | ppb | 5.5 | ppb |
| 04700-221-S | Clinic Bathroom Sink | 6.9 | ppb | | |
| 04700-211-S | Kindergarten Classroom Sink | 1.5 | ppb | | |
| 04700-213H-DF | Hallway Drinking Fountain | 0.5 | ppb | | |
| 04700-210-S | Kindergarten Classroom Sink | 0.4 | ppb | | |
| 04700-201-SWB | Sink with Bubbler in Room 201 | 19.9 | ppb | 3.0 | ppb |
| 04700-197-SWB1 | Sink with Bubbler Near Room 195/Left | 1.3 | ppb | | |
| 04700-197-SWB2 | Sink with Bubbler Near Room 195/Right | 1.5 | ppb | | |
| 04700-186-S1 | Art Room Sink | 1.4 | ppb | | |
| 04700-186-S2 | Art Room Sink | 2.5 | ppb | | |
| 04700-181-SWB | Sink with Bubbler in Cafeteria | 5.3 | ppb | | |
| 04700-146-S1 | Food Prep Sink | 27.4 | ppb | 2.2 | ppb |
| 04700-146-S2 | Food Service Sink - Hose Connection Spigot | 8.3 | ppb | | |
| 04700-146-S3 | Food Service Sink | 8.8 | ppb | | |
| 04700-146-S4 | Food Service Sink - Wash/Rinse | 3.9 | ppb | | |
| 04700-146-S5 | Food Service Sink - Hand Sink | 5.7 | ppb | | |
| 04700-108H-SWB | Hallway Sink with Bubbler | 0.7 | ppb | | |
| 04700-109-SWB | Sink with Bubbler near Room 104 | 0.9 | ppb | | |
| 04700-112-SWB | Sink with Bubbler in Classroom 112 | 3.3 | ppb | | |
| 04700-1118H-SWB | Hallway Sink with Bubbler | 0.6 | ppb | | |
| 04700-152-SWB | Sink with Bubbler in Music Room | 17.8 | ppb | | Repairs Pending |
| 04700-120-SWB | Sink with Bubbler Near Room 115 | 1.0 | ppb | | |
| 04700-123-SWB | Sink with Bubbler in Pre-K Room | 8.6 | ppb | | |
| 04700-128H-SWB | Hallway Sink with Bubbler | 3.2 | ppb | | |
| 04700-131-SWB | Sink with Bubbler near Pre-K Room | 2.3 | ppb | | |
| 04700-158-SWB | Sink with Bubbler in Teacher's Lounge | 3.9 | ppb | | |
| 04700-232-S | Sink in Teacher's Lounge Restroom | 2.1 | ppb | | |
| 04700-163-S | Sink in Library Workroom | 26.7 | ppb | | Repairs Pending |

** Resampling Results after elevated fixtures were removed and replaced.