

Carmody Middle School - Sampled 8/17/16				Resampled** 1/31/17	
CustomerSampleNumber	Description	Lead Result	Units	Lead Result	Unit
64200-109X-S	Sink in Library Work Room	1.8	ppb		
64200-160-S1	Food Service Sink-Hand Sink	33.4	ppb	11.0	ppb
64200-160-S2	Food Service Sink-Food Prep	5.1	ppb		
64200-160-S3	Food Service Sink-Sanitize	5.0	ppb		
64200-160-S4	Food Service Sink-Sanitize	1.9	ppb		
64200-160-S5	Food Service Sink-Sprayer	10.6	ppb		
64200-159-DF	Drinking Fountain in Cafeteria	1.3	ppb		
64200-168-S	Sink in Teacher's Lounge	2.5	ppb		
64200-168-IM	Ice Machine in Teacher's Lounge	0.5	ppb		
64200-114-S	Sink in Orchestra Classroom 114	4.4	ppb		
64200-114-SWB	Sink with Bubbler in Orchestra Classroom 114	1.9	ppb		
64200-176-S	Sink in Custodial Office	0.4	ppb		
64200-179-S	Sink in Storage Room by Custodial Office	46.2	ppb	5.9	ppb
64200-115-S1	Sink in Art Room 115	1.0	ppb		
64200-115-S2	Sink in Art Room 115	5.2	ppb		
64200-116-S1	Sink in Art Room 116	6.9	ppb		
64200-116-S2	Sink in Art Room 116	2.8	ppb		
64200-AUXGYM-DF	Drinking Fountain in Auxiliary Gym	1.7	ppb		
64200-GYM-DF	Drinking Fountain in Large Gym	1.4	ppb		
64200-144H-DF	Hallway Drinking Fountain near Elevator on 1st Floor	1.0	ppb		
64200-112-S	Sink in Consumer Science Room 112	16.0	ppb		Repairs Pending
64200-111-S	Sink in Kitchen Area of Classroom 111	13.2	ppb		
64200-143H-DF	Hallway Drinking Fountain near Classrooms 104 and 105	0.6	ppb		
64200-107-S	Sink in Classroom 107	0.9	ppb		
64200-228-S1	Sink in Science Classroom 228	0.6	ppb		
64200-228-S2	Sink in Science Classroom 228	0.5	ppb		
64200-228-S3	Sink in Science Classroom 228	1.0	ppb		
64200-228-S4	Sink in Science Classroom 228	1.5	ppb		
64200-227-S1	Sink in Science Classroom 227	1.3	ppb		
64200-227-S2	Sink in Science Classroom 227	4.3	ppb		
64200-227-S3	Sink in Science Classroom 227	2.6	ppb		
64200-227-S4	Sink in Science Classroom 227	0.6	ppb		
64200-226-S1	Sink in Science Classroom 226	0.9	ppb		
64200-226-S2	Sink in Science Classroom 226	1.0	ppb		
64200-226-S3	Sink in Science Classroom 226	1.2	ppb		
64200-226-S4	Sink in Science Classroom 226	0.9	ppb		
64200-219XH-DFL	Hallway Drinking Fountain across from Stairs on 2nd Floor/Left	<0.1 *	ppb		
64200-219XH-DFR	Hallway Drinking Fountain across from Stairs on 2nd Floor/Right	<0.1 *	ppb		
64200-212-S1	Sink in Science Classroom 212	0.7	ppb		
64200-212-S2	Sink in Science Classroom 212	0.8	ppb		
64200-212-S3	Sink in Science Classroom 212	0.5	ppb		
64200-212-S4	Sink in Science Classroom 212	1.8	ppb		
64200-213-S1	Sink in Science Classroom 213	4.2	ppb		
64200-213-S2	Sink in Science Classroom 213	1.5	ppb		
64200-213-S3	Sink in Science Classroom 213	1.1	ppb		
64200-213-S4	Sink in Science Classroom 213	2.0	ppb		
64200-214-S1	Sink in Science Classroom 214	2.2	ppb		
64200-214-S2	Sink in Science Classroom 214	0.6	ppb		
64200-214-S3	Sink in Science Classroom 214	2.2	ppb		
64200-214-S4	Sink in Science Classroom 214	1.3	ppb		
64200-257H-DFL	Hallway Drinking Fountain near Elevator on 2nd Floor/Left	<0.1 *	ppb		
64200-257H-DFR	Hallway Drinking Fountain near Elevator on 2nd Floor/Right	<0.1 *	ppb		
64200-238-S1	Sink in Science Prep Room 238	6.6	ppb		
64200-238-S2	Sink in Science Prep Room 238	1.2	ppb		
64200-122-S	Sink in Clinic	***1.0	ppb		

* This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.

** Resampling results after elevated fixtures were repaired, or removed and replaced.

*** This fixture was sampled on 1/31/17.