

| Conifer High School - Sampled 10/5/16 | | | | Resampled** 10/5/16 | |
|---------------------------------------|--|-------------|-------|---------------------|------|
| CustomerSampleNumber | Description | Lead Result | Units | Lead Result | Unit |
| 73600-C127-S1 | Food Service Sink-Hand Sink | 9.2 | ppb | | |
| 73600-C127-S2 | Food Service Sink-Sprayer | 125.7 | ppb | Repairs Pending | |
| 73600-C127-S3 | Food Service Sink-Food Prep | 13.5 | ppb | | |
| 73600-C127-S4 | Food Service Sink-Faucet over Disposal | 31.9 | ppb | Repairs Pending | |
| 73600-C127-S5 | Food Service Sink-Sprayer | 34.6 | ppb | 13.0 | ppb |
| 73600-C128-S1 | Food Service Sink-Hand Sink | 5.8 | ppb | | |
| 73600-C128-S2 | Food Service Sink-Sprayer over Sanitize/Rinse | 21.8 | ppb | 2.1 | ppb |
| 73600-C128-S3 | Food Service Sink-Sprayer over Rise/Wash | 2.4 | ppb | | |
| 73600-C128-S4 | Food Service Sink-Sprayer | 2.0 | ppb | | |
| 73600-C126-S | Food Service Sink-Hand Sink | 3.0 | ppb | | |
| 73600-B102H-WBFS | Hallway Water Bottle Filling Station outside of Cafeteria | <0.1 * | ppb | | |
| 73600-B102H-DF | Hallway Drinking Fountain outside of Cafeteria | <0.1 * | ppb | | |
| 73600-C107BA-S | Sink in Dressing Room C107BA | 17.2 | ppb | 3.9 | ppb |
| 73600-C110-S | Sink in Concession Area | 2.4 | ppb | | |
| 73600-C120-S | Sink in Storage Room C120 | 3.6 | ppb | | |
| 73600-D132-DF | Drinking Fountain in Small Gym | 0.6 | ppb | | |
| 73600-D110-DF | Drinking Fountain in Locker Room D110 | 1.5 | ppb | | |
| 73600-D116-S | Sink in Training Room D116 | 2.8 | ppb | | |
| 73600-D116-IM | Ice Machine in Training Room D116 | <0.1 * | ppb | | |
| 73600-D124-DF | Drinking Fountain in Locker Room D124 | 7.1 | ppb | | |
| 73600-D101-DFL | Drinking Fountain in Large Gym/Left | 1.9 | ppb | | |
| 73600-D101-DFR | Drinking Fountain in Large Gym/Right | 1.1 | ppb | | |
| 73600-D128-DF | Drinking Fountain in Locker Room D128 | 0.5 | ppb | | |
| 73600-D108-DF | Drinking Fountain in Locker Room D108 | 1.8 | ppb | | |
| 73600-D105-S | Sink in Locker Room D105 | 4.1 | ppb | | |
| 73600-D130-S | Sink in Locker Room D130 | 2.2 | ppb | | |
| 73600-B146-S | Sink in Store Room B146 | 1.5 | ppb | | |
| 73600-B143-S | Sink in Clinic | 3.6 | ppb | | |
| 73600-B112-S | Sink in Teacher's Lounge | 3.8 | ppb | | |
| 73600-B114-S | Sink in Library Work Room | 7.1 | ppb | | |
| 73600-A110-S2 | Sink in Laboratory A110 | 3.3 | ppb | | |
| 73600-A110-S3 | Sink in Laboratory A110 | 2.1 | ppb | | |
| 73600-A110-S4 | Sink in Laboratory A110 | 2.0 | ppb | | |
| 73600-A109-S | Sink in Science Prep Room A109 | 7.2 | ppb | | |
| 73600-A140H-DF | Hallway Drinking Fountain outside of Technology Lab A140 | 1.1 | ppb | | |
| 73600-A119-S | Sink in Classroom A119 | 1.9 | ppb | | |
| 73600-A123-S | Sink in Planning Room A123 | 2.0 | ppb | | |
| 73600-A130H-WBFS | Water Bottle Filling Station outside of Technology Lab A136 | <0.1 * | ppb | | |
| 73600-A130H-DF | Hallway Drinking Fountain outside of Technology Lab A136 | <0.1 * | ppb | | |
| 73600-A106-S1 | Sink in Laboratory A106 | 2.5 | ppb | | |
| 73600-A106-S2 | Sink in Laboratory A106 | 2.9 | ppb | | |
| 73600-A106-S3 | Sink in Laboratory A106 | 2.8 | ppb | | |
| 73600-A140-S | Sink in Technology Lab A140 | 5.2 | ppb | | |
| 73600-A136-S | Sink in Technology Lab A136 | 8.7 | ppb | | |
| 73600-A033-S1 | Sink in Kitchen Classroom A033 | 5.4 | ppb | | |
| 73600-A033-S2 | Sink in Kitchen Classroom A033 | 9.9 | ppb | | |
| 73600-A035-S | Sink in Classroom A035 | 8.8 | ppb | | |
| 73600-A037H-DFL | Hallway Drinking Fountain across from Kitchen Classroom A033/Left | 1.6 | ppb | | |
| 73600-A037H-DFR | Hallway Drinking Fountain across from Kitchen Classroom A033/Right | 3.2 | ppb | | |
| 73600-A024-S2 | Sink in Science Classroom A024 | 4.5 | ppb | | |
| 73600-A024-S3 | Sink in Science Classroom A024 (in back left corner of room) | 18.4 | ppb | 2.2 | ppb |
| 73600-A024-S4 | Sink in Science Classroom A024 | 3.9 | ppb | | |
| 73600-A011-S1 | Sink in Science Classroom A011 | 5.2 | ppb | | |
| 73600-A011-S2 | Sink in Science Classroom A011 | 3.8 | ppb | | |
| 73600-A011-S3 | Sink in Science Classroom A011 | 2.1 | ppb | | |
| 73600-A011-S4 | Sink in Science Classroom A011 | 1.6 | ppb | | |
| 73600-A012-S | Sink in Science Prep Room A012 | 8.6 | ppb | | |
| 73600-A001H-DFL | Hallway Drinking Fountain across from Classroom A005/Left | 1.0 | ppb | | |
| 73600-A001H-DFR | Hallway Drinking Fountain across from Classroom A005/Right | 2.6 | ppb | | |

| | | | | |
|--|---|--------|-----|--|
| 73600-A228H-DF | Hallway Drinking Fountain across from Work Room A202 | 1.3 | ppb | |
| 73600-A235H-DF | Hallway Drinking Fountain across from Computer Classroom A211 | 2.2 | ppb | |
| 73600-A202-S | Sink in Work Room A202 | 2.8 | ppb | |
| 73600-A229-S | Sink in Science Prep Room A229 | 3.9 | ppb | |
| 73600-A230-S2 | Sink in Laboratory A230 | 2.3 | ppb | |
| 73600-A230-S3 | Sink in Laboratory A230 | 2.1 | ppb | |
| 73600-A230-S4 | Sink in Laboratory A230 | 1.8 | ppb | |
| 73600-A231-S1 | Sink in Laboratory A231 | 3.3 | ppb | |
| 73600-A231-S2 | Sink in Laboratory A231 | 3.7 | ppb | |
| 73600-A231-S3 | Sink in Laboratory A231 | 8.5 | ppb | |
| 73600-B207-S1 | Sink in Art Room B207 | 12.3 | ppb | |
| 73600-B207-S2 | Sink in Art Room B207 | 10.2 | ppb | |
| 73600-B207-S3 | Sink in Art Room B207 | 4.4 | ppb | |
| 73600-B207-S4 | Sink in Art Room B207 | 9.8 | ppb | |
| 73600-B207-S5 | Sink in Art Room B207 | 10.5 | ppb | |
| 73600-B209-S1 | Sink in Art Room B209 | 1.1 | ppb | |
| 73600-B209-S2 | Sink in Art Room B209 | 4.6 | ppb | |
| 73600-B209-S4 | Sink in Art Room B209 | 11.9 | ppb | |
| 73600-B209-S5 | Sink in Art Room B209 | 3.8 | ppb | |
| 73600-B209-S6 | Sink in Art Room B209 | 2.8 | ppb | |
| 73600-B209-S7 | Sink in Art Room B209 | 3.1 | ppb | |
| 73600-B209-S8 | Sink in Art Room B209 | 4.9 | ppb | |
| 73600-B213-S3 | Sink in Art Room B213 | 4.8 | ppb | |
| 73600-B213-S4 | Sink in Art Room B213 | 4.2 | ppb | |
| 73600-B213-S5 | Sink in Art Room B213 | 4.6 | ppb | |
| 73600-B213-S6 | Sink in Art Room B213 | 2.5 | ppb | |
| 73600-B213-S7 | Sink in Art Room B213 | 1.6 | ppb | |
| 73600-B213-S8 | Sink in Art Room B213 | 0.8 | ppb | |
| 73600-A241-S | Sink in Classroom A239 | 3.7 | ppb | |
| 73600-B124-DF | Drinking Fountain in Work Room B124 | 0.9*** | ppb | |
| 73600-B124-S | Sink in Work Room B124 | 2.1*** | ppb | |
| 73600-B213-S2 | Art Room Sink | 7.5*** | ppb | |
| 73600-B213-S3 | Art Room Sink | 5.1*** | ppb | |
| 73600-C118-S1 | Sink in Dressing Room C118 | 5.1*** | ppb | |
| * This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab. | | | | |
| ** Resampling results after elevated fixtures were repaired, or removed and replaced. | | | | |
| *** This fixture was sampled on 1/27/17. | | | | |