

Lakewood High School - Sampled 8/2/16			
CustomerSampleNumber	Description	Lead Result	Units
77000-E135H-WBFS	Hallway Water Bottle Filling Station across from Art Room E103	0.1	ppb
77000-E135H-DF	Hallway Drinking Fountain across from Art Room E103	0.2	ppb
77000-E103-S1	Sink in Art Room E103	0.7	ppb
77000-E103-S2	Sink in Art Room E103	3.7	ppb
77000-E103-S3	Sink in Art Room E103	4.4	ppb
77000-E102-S	Sink in Dark Room E102	3.6	ppb
77000-E104-S1	Sink in Art Room E104	4.4	ppb
77000-E104-S2	Sink in Art Room E104	3.6	ppb
77000-E104-S3	Sink in Art Room E104	3.8	ppb
77000-E104-S4	Sink in Art Room E104	3.0	ppb
77000-E105-S1	Sink in Art Room E105	3.9	ppb
77000-E105-S2	Sink in Art Room E105	3.6	ppb
77000-E105-S3	Sink in Art Room E105	5.9	ppb
77000-E105-S4	Sink in Art Room E105	5.3	ppb
77000-E112-S	Sink in Voc Lab E112	8.2	ppb
77000-E125-S	Sink in Band Room E125	0.3	ppb
77000-D134H-DF	Hallway Drinking Fountain across from Band Room	0.3	ppb
77000-C131XH-DF	Hallway Drinking Fountain outside of Music Room C137	0.2	ppb
77000-E127-DF	Drinking Fountain in Weight Room E127	0.2	ppb
77000-C141-DF	Drinking Fountain in Choir Room C141	0.3	ppb
77000-F105-IM	Ice Machine in Training Room F105	1.3	ppb
77000-D132-IM	Ice Machine in Food Service Area	<0.1 *	ppb
* This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.			