

| Little Elementary School - Sampled 7/26/16 | | | | Resampled** 8/26/16, 11/23/16 | |
|--|--|-------------|-------|-------------------------------|-----------------|
| CustomerSampleNumber | Description | Lead Result | Units | Lead Result | Unit |
| 23500-REC-067-DF | Drinking Fountain in TEMP REC-067 | 0.9 | ppb | | |
| 23500-REC-114-DF | Drinking Fountain in TEMP REC-114 | 0.3 | ppb | | |
| 23500-135H-DF | Hallway Drinking Fountain Outside of Art Room | 11.4 | ppb | | |
| 23500-101-S | Sink in Kindergarten Classroom 101 | 6.9 | ppb | | |
| 23500-101-SWB | Sink with Bubbler in Kindergarten Classroom 101 | 23.1 | ppb | 3.9 | ppb |
| 23500-141-S | Sink in Kindergarten Classroom 141 | 13.1 | ppb | | |
| 23500-141-SWB | Sink with Bubbler in Kindergarten Classroom 141 | 3.5 | ppb | | |
| 23500-140H-S | Hallway Sink across from Main Office | 5.1 | ppb | | |
| 23500-140H-SWB | Hallway Sink with Bubbler across from Main Office | 4.5 | ppb | | |
| 23500-131AX-S | Sink in Clinic | 7.2 | ppb | | |
| 23500-131AX-SWB | Sink with Bubbler in Clinic | 3.2 | ppb | | |
| 23500-129-S | Sink in Planning Room 129 | 24.3 | ppb | 7.2 | ppb |
| 23500-105-S | Sink in Teacher's Lounge | 1.4 | ppb | | |
| 23500-165-S1 | Food Service Sink-Hand Sink | 327.8 | ppb | 3.7 | ppb |
| 23500-165-S2 | Food Service Sink-Dish Wash/Sprayer | 18.7 | ppb | | Repairs Pending |
| 23500-165-S3 | Food Service Sink-Wash/Rinse | 7.8 | ppb | | |
| 23500-165-S4 | Food Service Sink-Rinse/Sanitize | 16.4 | ppb | 8.0 | ppb |
| 23500-165-S5 | Food Service Sink-Food Prep | 8.9 | ppb | | |
| 23500-165-S6 | Food Service Sink-Food Prep/Hose Connector Spigot | 23.8 | ppb | | Fixture Removed |
| 23500-176H-S1 | Hallway Sink Outside of Kitchen | 3.3 | ppb | | |
| 23500-176H-SWB1 | Hallway Sink with Bubbler Outside of Kitchen | 2.2 | ppb | | |
| 23500-176H-S2 | Hallway Sink Outside of Kitchen | 5.1 | ppb | | |
| 23500-176H-SWB2 | Hallway Sink with Bubbler Outside of Kitchen | 3.0 | ppb | | |
| 23500-182A-S | Sink in Classroom 182A | 2.6 | ppb | | |
| 23500-182A-SWB | Sink with Bubbler in Classroom 182A | 1.6 | ppb | | |
| 23500-167-S | Sink in Classroom 167 | 0.6 | ppb | | |
| 23500-167-SWB | Sink with Bubbler in Classroom 167 | 0.3 | ppb | | |
| 23500-168-S | Sink in Classroom 168 | 1.0 | ppb | | |
| 23500-168-SWB | Sink with Bubbler in Classroom 168 | 0.3 | ppb | | |
| 23500-124-S | Sink in Classroom 124 | 0.5 | ppb | | |
| 23500-124-SWB | Sink with Bubbler in Classroom 124 | 0.8 | ppb | | |
| 23500-137H-S | Hallway Sink across from Classroom 169 | 4.4 | ppb | | |
| 23500-137H-SWB | Hallway Sink with Bubbler across from Classroom 169 | 7.4 | ppb | | |
| 23500-111-S | Sink in Classroom 111 | 1.1 | ppb | | |
| 23500-113-S | Sink in Classroom 113 | 1.4 | ppb | | |
| 23500-177-S | Sink in Classroom 177 | 1.0 | ppb | | |
| 23500-174H-S | Hallway Sink across from Classroom 169B | 4.6 | ppb | | |
| 23500-174H-SWB | Hallway Sink with Bubbler across from Classroom 169B | 7.8 | ppb | | |
| 23500-172-S | Sink in Classroom 172 | 0.7 | ppb | | |
| 23500-138-S1 | Art Room Sink | 8.7 | ppb | | |
| 23500-138-S2 | Art Room Sink | 5.7 | ppb | | |
| 23500-147C-S | Sink in Library Work Room | 21.5 | ppb | 1.5 | ppb |
| 23500-149-S | Sink in Library Work Room | 35.9 | ppb | 2.5 | ppb |

** Resampling results after elevated fixtures were repaired, or removed and replaced.