

Mt Evans OELS - Sampled 11/22/16			
CustomerSampleNumber	Description	Lead Result	Unit
59100-ResB-Kitchen-S	Sink in Kitchen in Residence B	< 0.1 *	ppb
59100-ResD-Kitchen-S	Sink in Kitchen in Residence D	2.5	ppb
59100-ResD-Bath1-S	Sink in Restroom on left in Residence D	1.7	ppb
59100-ResD-Bath2-S	Sink in Restroom on right in Residence D	1.9	ppb
59100-Dining Hall-S	Sink in Dining Hall	1.3	ppb
59100-Dining Hall-Kitchen-S1	Dining Hall Kitchen Sink-Sprayer	1.1	ppb
59100-Dining Hall-Kitchen-S2	Dining Hall Kitchen Sink-Hand Sink	0.7	ppb
59100-Dining Hall-Kitchen-S3	Dining Hall Kitchen Sink-Dish Wash	0.6	ppb
59100-Dining Hall-Kitchen-S4	Dining Hall Kitchen Sink-Food Prep	0.8	ppb
59100-Conf Center-Spigot	Spigot in front of Conference Center	3.6	ppb
59100-Conf Center-Bath1-S	Sink in Restroom on left in Conference Center	5.8	ppb
59100-Conf Center-Kitchen-S	Sink in Kitchen in Conference Center	1.7	ppb
59100-Conf Center-Bath2-S	Sink in Restroom on right in Conference Center	2.4	ppb
59100-ResA-Kitchen-S	Sink in Kitchen in Residence A	0.7	ppb
59100-ResA-Bath1-S	Sink in Restroom on left in Residence A	1.4	ppb
59100-ResA-Bath2-S	Sink in Restroom on right in Residence A	0.7	ppb
59100-Dodge Lodge-Serving-S	Sink in Serving Area in Dodge Lodge	7.5	ppb
59100-Dodge Lodge-Kitchen-S	Sink in Kitchen in Dodge Lodge	2.8	ppb
59100-Dodge Lodge-Bath1-S	Sink in Restroom on 1st Floor of Dodge Lodge	5.7	ppb
59100-Dodge Lodge-Bath2-S	Sink in Restroom on 2nd Floor of Dodge Lodge in front of stairs	3.6	ppb
59100-Dodge Lodge-Bath3-S	Sink in Restroom on 2nd Floor of Dodge Lodge next to stairs	4.2	ppb
59100-Central Shower-Boys-S	Sink in Boy's Central Shower Area	1.3	ppb
59100-Central Shower-Girls-S1	Sink in Girl's Central Shower Area/Left	0.9	ppb
59100-Central Shower-Girls-S2	Sink in Girl's Central Shower Area/Right	1.4	ppb
59100-Main Office-Bath-S1	Sink in Main Office Restroom/Left	7.4	ppb
59100-Main Office-Bath-S2	Sink in Main Office Restroom/Right	8.1	ppb
59100-Main Office2-Kitchen-S	Sink in 2nd Floor Main Office Kitchen	4.2	ppb
59100-Main Office2-Bath-S	Sink in 2nd Floor Main Office Restroom	1.7	ppb
59100-Pumphouse-S	Sink in Pump house	1.1	ppb
59100-Mt.Epaulet-DF	Drinking Fountain in Mt Epaulet	15.6	ppb
59100-Mt.Epaulet-Bath1-S1	Sink in Restroom on left in Mt Epaulet/Left	1.7	ppb
59100-Mt.Epaulet-Bath1-S2	Sink in Restroom on left in Mt Epaulet/Middle	7.8	ppb
59100-Mt.Epaulet-Bath1-S3	Sink in Restroom on left in Mt Epaulet/Right	6.0	ppb
59100-Mt.Epaulet-Bath2-S	Sink in Restroom on right in Mt Epaulet	1.2	ppb
59100-MtWarren-DF	Drinking Fountain in Mt Warren	2.0	ppb
59100-MtWarren-Bath-S1	Sink in Restroom in Mt Warren/Left	2.7	ppb
59100-MtWarren-Bath-S2	Sink in Restroom in Mt Warren/Middle	3.9	ppb
59100-MtWarren-Bath-S3	Sink in Restroom in Mt Warren/Right	8.9	ppb
59100-Bear Ham-DF	Drinking Fountain in Bear Ham Rec Center	1.1	ppb
59100-Bear Ham-Boys-S	Sink in Boy's Restroom in Bear Ham Rec Center	1.7	ppb
59100-Bear Ham-Girls-S	Sink in Girl's Restroom in Bear Ham Rec Center	1.1	ppb
59100-Mt Spalding-DF	Drinking Fountain in Mt Spalding	12.2	ppb
59100-Mt Spalding-Bath1-S	Sink in Restroom on left in Mt Spalding	8.7	ppb
59100-Mt Spalding-Bath2-S1	Sink in Restroom on right in Mt Spalding/Left	1.9	ppb
59100-Mt Spalding-Bath2-S2	Sink in Restroom on right in Mt Spalding/Middle	2.9	ppb
59100-Mt Spalding-Bath2-S3	Sink in Restroom on right in Mt Spalding/Right	4.6	ppb
59100-Clinic-S	Sink in Clinic	3.6	ppb
59100-Clinic-Bath-S	Sink in Clinic Restroom	0.3	ppb

59100-Mt Susan-DF	Drinking Fountain in Mt Susan	1.4	ppb
59100-Mt Susan-Bath1-S	Sink in Restroom on left in Mt Susan	1.1	ppb
59100-Mt Susan-Bath2-S1	Sink in Restroom on right in Mt Susan/Left	1.1	ppb
59100-Mt Susan-Bath2-S2	Sink in Restroom on right in Mt Susan/Middle	1.0	ppb
59100-Mt Susan-Bath2-S3	Sink in Restroom on right in Mt Susan/Right	0.7	ppb
59100-Mt Rosalie-DF	Drinking Fountain in Mt Rosalie	0.6	ppb
59100-Mt Rosalie-Bath1-S1	Sink in Restroom on left in Mt Rosalie/Left	0.4	ppb
59100-Mt Rosalie-Bath1-S2	Sink in Restroom on left in Mt Rosalie/Middle	0.8	ppb
59100-Mt Rosalie-Bath1-S3	Sink in Restroom on left in Mt Rosalie/Right	0.8	ppb
59100-Mt Rosalie-Bath2-S	Sink in Restroom on right in Mt Rosalie	2.9	ppb
59100-Barn-S	Sink in Barn	9.1	ppb
59100-Astronomy-DF	Drinking Fountain in Astronomy Building	7.1	ppb
59100-Astronomy-Bath1-S	Sink in Restroom on the left in the Astronomy Building	3.1	ppb
59100-Astronomy-Bath2-S	Sink in Restroom on the right in the Astronomy Building	2.3	ppb
59100-ResE-Kitchen-S	Sink in Kitchen in Residence E	1.1	ppb
59100-ResE-Bath1-S	Sink in Restroom on left in Residence E	0.9	ppb
59100-ResE-Bath2-S	Sink in Restroom on right in Residence E	1.3	ppb
* This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.			